

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 096 / 66-00-05531-00-1 Block Unit #011-017

County: Montgomery

Municipality: Whitpain Township

Address: 99 Plymouth Road

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – rear	
3	House – façade and east addition	
4	Barn	
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 096 Tax Parcel/Other No.: 66-00-05531-00-1 Block Unit #011-017

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 99 Plymouth Road Historic Name:

Other Name:

Owner Name/Address: Saly Glassman & Allan Syphers P.O. Box 559 Gwynedd Valley PA 19437

Owner Category: x Private Public-local Public-state Public-federal

Resource Category: x Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 3

USGS Quad: 1. Lansdale 2.

UTM A. C.

References: B. D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence 1900 Dwelling

B.

C.

D.

Particular Type: A.

B.

C.

D.

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling

B.

C.

D.

PHYSICAL DESCRIPTION

Architectural Classification: A. Colonial Revival

B. C.

D. Other:

Exterior Materials: Foundation Roof wood shingles

Walls stucco Walls

Other Other

Structural System: 1. 2.

Width 6 bay Depth Stories/Height 2.5

HISTORICAL INFORMATION

Year Built: ca. 1900 Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status:

Classification: This large property with its architecturally significant exterior is a Class II resource.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: _____096_____ Tax Parcel/Other No.: 66-00-05531-00-1 Block Unit #011-017
County: Montgomery 091 Municipality: Whitpain Township
Address: 99 Plymouth Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is a large complex Colonial Revival house with Federal details. The core is a six bay, two and a half story house built c. 1900 and clad in stucco. Two interior end chimneys puncture the roof in the gable ends. The end gabled roof is clad in slate shingles. On the façade are four gabled roof dormers with two windows each. The sides of the dormers are clad in wooden shingles. Molded eaves frame the roof. There are six windows on the second floor, each with shutters. A pent roof separates the first and second floors and is broken by a one story entry porch with a molded gable supported by two round columns. Off the left side of the façade is an enclosed porch composed of bands of windows separated by round columns supporting the hipped roof. On the east end of the 25 x 50 core is a large two story addition 45 feet long. This addition has a mixture of gables and a flowing roof with two small gabled roof dormers. There are two chimneys on this addition. The first floor has a band of windows separated by the door with a gabled entry hood supported by molded braces. First floor windows have paneled shutters while the second floor windows have louvered shutters.

Associated resources:

- (1) **Barn.** This one and a half story, end-gabled barn has two gabled roof dormers and a large one story porch on the façade. Two unfluted pilasters and four unfluted columns support the porch. Wood shingles cover the gables of the barn, and clapboards cover the remainder. A small eight-sided cupola on top of the barn supports a weather vane and is louvered.
- (2) **Shed/Stable.** Frame, end gabled roofed structure. [no photo]

Classification: This large property with its architecturally significant exterior is a Class II resource.



